800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

Transmittal Letter 16-03

December 18, 2015

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs,EFFECTIVE UPON PUBLICATION Identified as follows: **AIRAC FDC FDC** STATE CITY **AIRPORT SUBJECT** DATE **NUMBER** DATE Takeoff Minimums Hartington NE Muni/Bud Becker 5/0057 12/02/15 and (Obstacle) DP, 4-Feb-16 Hartington Fld Orig

AIRAC Date: 4 February 2016

FDC **5/0057** 0B4 ODP HARTINGTON MUNI/ BUD BECKER FLD, HARTINGTON, NE. TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES ORIG... TAKEOFF MINIMUMS: RWY 3/21: NA - ENVIRONMENTAL. ALL OTHER DATA REMAINS AS PUBLISHED.

THIS IS **TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES, ORIG-A.** 1512012152-PERM